

3-PHASE TRACK SPOT LIGHT S220

Please read instructions before commencing installation and retain for future reference.

SPECIFICATIONS

- **Lamp Type:** 1x GU10 | 35W MAX
- **Material:** Aluminium
- **Ingress Protection:** IP 20 Protection against entry of solid objects greater than 12mm in diameter.

INSTALLATION INSTRUCTIONS

⚠ Electrical products can cause death, injury, or property damage. Maintenance and installation should only be carried out by a professional electrician.

- Ensure the main power supply is switched off.
- Complete the 3-phase track system according to your preferences.
- Connect the wires and power cord following the system installation manual.
- Make sure all connections are secure and tight.
- Add a GU10 bulb into the lampholder and fix the lamp-ring by screwing it.
- Install the 3-phase spot in the desired position by inserting it into the tracks.
- Move 3-phase switch to position 1, 2 or 3 to work as follows.
Position 1: The spot is connected to the first phase (L1) of the system.
Position 2: The spot is connected to the second phase (L2) of the system.
Position 3: The spot is connected to the third phase (L3) of the system.
- Reconnect the power supply.

WARNING

- ⚠** Make sure that the products are installed properly before connecting to electricity. Do not cover the luminaire.
- Do not exceed the maximum wattage rating of the lamp.
- If the light source is contained in this luminaire (integrated LED), it shall only be replaced by the manufacturer, his service agent, or a similarly qualified person.
- Bulbs not included with the lighting fixtures.

